

RECEIVED

Revised 10/03

2003 OCT 15 A 9:35

STATE OF COLORADO

CORRES. CONTROL
INCOMING LTR NO.

00953 RFO3

DUE DATE
ACTION

Bill Owens, Governor

Douglas H. Benevento, Executive Director

CORRESPONDENCE
CONTROL

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S.
Denver, Colorado 80246-1530
Phone (303) 692-2000
TDD Line (303) 691-7700
Located in Glendale, Colorado

Laboratory and Radiation Services Division
8100 Lowry Blvd.
Denver, Colorado 80230-6928
(303) 692-3090

<http://www.cdphe.state.co.us>



Colorado Department
of Public Health
and Environment

DIST.	LTR	END
BERARDINI, J. H.	X	
BOGNAR, E. S.	X	
BROOKS, L.	X	
BUTLER, L.	X	
CROCKETT, G. A.	X	
DECK, C. A.	X	
DEGENHART, K. R.	X	
DIETER, T. J.	X	
DIETERLE, S. E.	X	
FERRERA, D. W.	X	
GIACOMINI, J. J.	X	
HIETT, S. B.	X	
ISOM, J. H.	X	
LINDSAY, D. C.	X	
LONG, J. W.	X	
LYLE, J. L.	X	
MARTINEZ, L. A.	X	
NAGEL, R. E.	X	
NORTH, K.	X	
PARKER, A. M.	X	
RODGERS, A. D.	X	
SHELTON, D. C.	X	
SPEARS, M. S.	X	
TRICE, K. D.	X	
TUOR, N. B.	X	
WILLIAMS, J. L.	X	
ZAHM, C.	X	
Wiemelt, K.	X	
Freiboth, C.	X	
Nesta, S.	X	

October 9, 2003

Mr. Joe Legare

Acting Assistant Manager for Environment and Stewardship

U.S. Department of Energy, Rocky Flats Field Office

10808 Highway 93, Unit A

Golden, CO 80403-8200

RE: Closeout Report for Buildings 372, 372A, 308B, & 308D

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the Closeout Report for Buildings 372, 372A, 308B, and 308D, dated October 6, 2003. We appreciate being provided this Closeout Report for our information.

Closeout Reports should identify all removal activity and include a map of the facility identifying the structures involved, those removed, and the location of remaining infrastructure and its condition. Infrastructure includes all remaining materials and their location, and includes slabs, piers, footings, water pipes, gas lines, electrical conduits, drain lines, PWLs, sewer lines, etc. These maps are necessary for possible ER and/or future stewardship concerns. The discussion provided for B308B and D does not specifically address the infrastructure removed or remaining. It cannot be determined if the entire slab or sump has been removed, or if in-ground utilities (pipes) remain. Although a map is provided that shows the location of B308B and 308D, and indicates a basic location for the electrical disconnects, this map is not sufficient to provide the detail necessary. As such, we would appreciate being provided a revised Closeout Report for Buildings 308B and 308D addressing these concerns.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

Sincerely,

Steven H. Gunderson

Steven H. Gunderson
RFCA Project Coordinator

COR. CONTROL	X
ADMN. RECORD	X
PATS/130	

Reviewed for Addressee
Corres. Control RFP

10/15/03
Date By

Ref. Ltr. #

DOE ORDER #

5400.1

cc: Steve Tower, DOE
Tim Rehder, EPA
Karen Wiemelt, KH
David Abelson, RFCLOG

Cameron Freiboth, KH
Dave Shelton, KH
Steve Nesta, KH
Administrative Records Building T130G

ADMIN RECORD

IA-A-001711